



**Product Obsolescence Notification
SM Series Seam Welders**

Date: July 31, 2020
What: Obsolescence notification BENCHMARK SM Series Seam Welders
Affected Products: SM85-05XXXXXXX
Current Replacement Product: SM85-06XXXXXXX

AMADA WELD TECH, INC. has for many years supplied reliable equipment to the electronic assembly marketplace. However, in accordance with AMADA WELD TECH’s product obsolescence policy, we are hereby giving notice of our product’s obsolescence and end of the post obsolescence period. Listed below are the last shipment dates for all previous generations of AF series seam welders. AMADA WELD TECH provides a 7 year post obsolescence support.

| Part Numbers | Obsolescence Date | Post Obsolescence Date | Replacement Product |
|----------------|-------------------|------------------------|---------------------|
| SM85-05XXXXXXX | 07/2020 | 07/2027 | SM85-06XXXXXXX |

In cases wherein our product have reached the end of post obsolescence support, we will continue to provide support for these products on a best effort basis. However, we cannot guarantee that the problem can be resolved or if all spare parts will be available. For the other models, we will continue support until the end of post obsolescence period, and then support as best as possible.

AMADA WELD TECH goes beyond the industry standard to provide our customers a stable platform, as evidenced by our DP, HF2, and other product lines, which are sometimes in service for 20+ years. As with any technical product, components can go obsolete. AMADA WELD TECH is proactive to identify replacement components and maintain service inventory to support customers until replacement has been identified.

We look forward to support you with these products and your process now and in the future. Let us know if you have any further comments or concerns.

Regards,

Mark Sunico
Product Engineer